Norman H. Bangerter

Governor

Suzanne Dandoy, M.D., M.P.H.

Executive Director

October 20, 1986 538-6146

Mr. Tom B. Larsen, Ph.D.
Manager of Environmental Affairs
Inspiration Gold Incorporated
P. O. Box 1559
Clay Pool, Arizona 85532



DIVISION OF OIL, GAS & MINING

RE: Goldstrike Mine
Plan of Operation
Comments

Dear Mr. Larsen:

UTAH

We have reviewed the plan of operation for the Goldstrike Mine, Washington County, Utah, to identify major conceptual concerns which we might have with the proposed project. These concerns are listed below:

- a. A double liner system with a leak detention system will be required beneath the ponds.
- b. Whether or not a liner will be required beneath the tailings pile and the type of liner which may be required will be determined by how effectively and consistently the tailings can be neutralized. In addition, the amount and type of other constituents found in the tailings will have an impact. Finally, the quality of the ground water beneath the ponds and the nature and condition of the natural material which exists beneath the tailings piles will also effect the requirement for a liner.
- c. Provisions for controlling surface runoff around waste piles, tailings piles, leach ponds, the process areas, and disturbed surface area in general will be required.

These are the general comments of the Bureau with regard to the project.

Inspiration Gold Incorporated Page Two Other Bureaus in the Division of Environmental Health, such as Public Water Supplies and Air Quality, should be involved in the project review. Please call if there are questions. Sincerely, Charles G. Dietz, P.E. Environmental Engineer Bureau of Water Pollution Control. CGD:mw cc: Keith Droste, Inspiration Gold, Inc. Wayne Headberg, Oil, Gas, and Mining Wayne Thomas, S. W. Dist. Health Dept. 0179B